


Hoonah Airport

Pavement Condition Index (PCI) Measured Values for the Year 2003

Minimum PCI for Runway = 70
Minimum PCI for Taxiways and Aprons = 60

[] Branch-Section Identifier

Airport Code: HNH
Site Number: 50321.01.*A




Hoonah Airport

Pavement Condition Index (PCI) Predicted Values for the Year 2004

Minimum PCI for Runway = 70
Minimum PCI for Taxiways and Aprons = 60

[] Branch-Section Identifier

Airport Code: HNH
Site Number: 50321.01.*A




Hoonah Airport

Pavement Condition Index (PCI) Predicted Values for the Year 2005

Minimum PCI for Runway = 70
Minimum PCI for Taxiways and Aprons = 60

[] Branch-Section Identifier

Airport Code: HNH
Site Number: 50321.01.*A



Hoonah Airport


Pavement Condition Index (PCI) Predicted Values for the Year 2006

Minimum PCI for Runway = 70
Minimum PCI for Taxiways and Aprons = 60

[] Branch-Section Identifier

Airport Code: HNH
Site Number: 50321.01.*A

PCI Values	General Pavement Recommendations
85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct



0 500 1,000
Feet



Map Compiled July 2003
by Statewide Pavement Management, AK DOT&PF


Hoonah Airport

Pavement Condition Index (PCI) Predicted Values for the Year 2007

Minimum PCI for Runway = 70
Minimum PCI for Taxiways and Aprons = 60

[] Branch-Section Identifier

Airport Code: HNH
Site Number: 50321.01.*A



Hoonah Airport


Pavement Condition Index (PCI) Predicted Values for the Year 2008

Minimum PCI for Runway = 70
Minimum PCI for Taxiways and Aprons = 60

[] Branch-Section Identifier

Airport Code: HNH
Site Number: 50321.01.*A

PCI Values	General Pavement Recommendations
85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct



0 500 1,000
Feet



Map Compiled July 2003
by Statewide Pavement Management, AK DOT&PF